

Fig. 15

The diagram illustrates a complex mechanical assembly in cross-section. A coordinate system is defined with the z -axis pointing upwards, the x -axis pointing to the right, and the y -axis pointing out of the page. The assembly is divided into two main sections, A and B, by a vertical dashed line. Section A (on the left) includes components labeled 1, 1B, 5.1, 5.2, 5.5, 6.1a, 6.1aB, 6.2a, 6.5, 6.6b, 6.8, 21.3, 21.3B, 21.5, 23, 26.1, 30, 31, 32, 33, 34, 35, 36. Section B (on the right) includes components labeled 5.1B, 5.2B, 5.5B, 6.0, 6.0B, 6.1a, 6.2a, 6.5, 6.6b, 6.8, 21.3, 21.3B, 21.5, 23, 26.1, 30, 31, 32, 33, 34, 35, 36. The central part of the assembly features a curved surface and a central shaft. Handwritten notes y_p and $-x_n$ are present near the central chamber. The diagram is labeled 'Fig. 15' at the top.




Fig. 15

